Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

 491
 2324 WEST 13TH ST
 NY LTANKS
 \$105999740

 NNW
 2324 WEST 13TH ST
 N/A

1/2-1 0.759 mi. 4010 ft. BROOKLYN, NY

 Relative:
 LTANKS:

 Higher
 Name:
 2324 WEST 13TH ST

 Actual:
 Address:
 2324 WEST 13TH ST

 9 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 0305649 / 2006-06-06

 Facility ID:
 0305649

 Site ID:
 132270

 Spill Date:
 2003-08-27

 Spill Cause:
 Tank Test Failure

Spill Source: Institutional, Educational, Gov., Other

Spill Class: B3

Cleanup Ceased: Not reported SWIS: 2401
Investigator: HRPATEL Referred To: Not reported Reported to Dept: 2003-08-27 CID: 205

Water Affected:

Spill Notifier:

Responsible Party
Last Inspection:

Recommended Penalty:

Meets Standard:

UST Involvement:

Remediation Phase:

Date Entered in Computer:

Seponsible Party

Not reported

False

False

False

0

2003-08-27

Date Entered In Computer: 2003-08-27 Spill Record Last Update: 2006-06-19

Spiller Name: NAPHTALI POLLACK

Spiller Company: OTSAR INC.

Spiller Address: 2324 WEST 13TH ST

Spiller County: 001
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extention: Not reported

DEC Region: 2
DER Facility ID: 113905
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead DEC Field was

SANGESLAND sent TTF letter 11/4/05 I spoke with the consultant after reviewing the soil data and indicated that one groundwater sample just below the tank location should be obtained and submitted. Jim Lister 1/20/06 I spoke with the consultant, Kevin O'Connor of Action Environmental (516-781-3000) and indicated that the gw sample indicated standards violations for the same semivolatiles that had been a problem in the soil, chrysene and benzo(b)Flouranthene. I indicated that maybe the temporary well hadn't been installed properly or not developed properly but that I would leave it to him to decide if another well should be installed or soil needs to be removed. He will get back to me. Jim Lister 06/01/06-Hiralkumar Patel. Left message for Kevin. 06/02/06-Hiralkumar Patel. Received message from Kevin. Left message for Kevin requesting lab results for soil and groundwater samples at site with site plan including sampling location. 06/05/06-Hiralkumar Patel. received message from

Kevin (Cell: 516-236-7468). left message for Kevin. 06/06/06-Hiralkumar Patel. REceived fax from Kevin, contains report. abstract of letter report: - two 550 gal USTs were filled with oil

Map ID MAP FINDINGS

Direction Distance Elevation

Site EDR ID Number

Database(s) EPA ID Number

once and never used. - tanks were full at the time of removal - tanks had failed a test due to the fact that one of the bung holes at the top of the tank was not properly closed. - at time of removal neither tank had any holes and the piping was in good condition - there was no odor and no signs of contaminated soil - two end point samples taken (1 bottom and 1 side walls) - little exceedence of SVOCs noted in samples - groundwater sample taken later - little exceedence of SVOCs found in water sample based on available information, case closed. 06/19/06-Hiralkumar Patel. Received call from Kevin. he asked to send NFA at following address: Otsar family services 2324 west 13th street brooklyn, ny 11223 sent NFA to above address. faxed letter to Kevin(FAX: 516-781-3085)."

Remarks:

All TTF:

Facility ID: 0305649 Spill Number: 0305649 Spill Tank Test: 1528623 Site ID: 132270 Tank Number: 1 Tank Size: 550 Material: 0001 EPA UST: Not reported UST: Not reported Cause: Not reported Not reported Source:

Test Method: 03

Test Method 2: Horner EZ Check I or II

Leak Rate: .00

Gross Fail: Not reported Modified By: Spills Last Modified Date: Not reported

All Materials:

Site ID: 132270 Operable Unit ID: 874096 Operable Unit: 01 Material ID: 502895 Material Code: 0001A Material Name: #2 fuel oil Case No.: Not reported Material FA: Petroleum Quantity: .00 Units: G .00 Recovered:

Oxygenate: Not reported